

<<表面形貌的光学测量>>

图书基本信息

书名：<<表面形貌的光学测量>>

13位ISBN编号：9787030344748

10位ISBN编号：703034474X

出版时间：2012-6

出版单位：科学出版社

作者：里奇

页数：323

字数：501250

版权说明：本站所提供下载的PDF图书仅提供预览和简介，请支持正版图书。

更多资源请访问：<http://www.tushu007.com>

<<表面形貌的光学测量>>

内容概要

本书介绍了表面形貌测量领域中一系列国际标准规范。
复杂的准则都是基于新的测量技术而产生的。
目前有很多用来测量表面形貌新的光学技术，每种方法都有其优点以及局限性。
本书既适用于业界及学术研究领域的工程人员，也适用于相关领域的研究生及高年级本科生。

<<表面形貌的光学测量>>

书籍目录

1 Introduction to Surface Texture Measurement Richard Leach
 1.1 Surface Texture Measurement
 1.2 Surface Profile and Areal Measurement
 1.3 Areal Surface Texture Measurement
 1.4 Surface Texture Standards and GPS
 1.4.1 Profile Standards
 1.4.2 Areal Specification Standards
 1.5 Instrument Types in the ISO 25178 Series
 1.5.1 The Stylus Instrument
 1.5.2 Scanning Probe Microscopes
 1.5.3 Scanning Electron Microscopes
 1.5.4 Optical Instrument Types
 1.6 Considerations When Choosing a Method
 Acknowledgements
 References
 2 Some Common Terms and Definitions Richard Leach
 2.1 Introduction
 2.2 The Principal Aberrations
 2.3 Objective Lenses
 2.4 Magnification and Numerical Aperture
 2.5 Spatial Resolution
 2.6 Optical Spot Size
 2.7 Field of View
 2.8 Depth of Field and Depth of Focus
 2.9 Interference Objectives
 Acknowledgements
 References
 3 Limitations of Optical 3D Sensors Gerd H?usler, Svenja Ettl
 3.1 Introduction: What Is This Chapter About?
 3.2 The Canonical Sensor
 3.3 Optically Rough and Smooth Surfaces
 3.4 Type Sensors: Triangulation
 3.5 Type and Type Sensors: Interferometry
 3.6 Type Sensors: Deflectometry
 3.7 Only Four Sensor Principles?
 3.8 Conclusion and Open Questions
 References
 4 Calibration of Optical Surface Topography Measuring Instruments Richard Leach, Claudiu Giusca
 4.1 Introduction to Calibration and Traceability
 4.2 Calibration of Surface Topography Measuring Instruments
 4.3 Can an Optical Instrument Be Calibrated?
 4.4 Types of Material Measure
 4.5 Calibration of Instrument Scales
 4.5.1 Noise
 4.5.2 Residual Flatness
 4.5.3 Amplification, Linearity and Squareness of the Scales
 4.5.4 Resolution
 4.6 Relationship between the Calibration, Adjustment and Measurement Uncertainty
 4.7 Summary
 Acknowledgements
 References
 5 Chromatic Confocal Microscopy Francois Blateyron
 5.1 Basic Theory
 5.1.1 Confocal Setting
 5.1.2 Axial Chromatic Dispersion
 5.1.3 Spectral Decoding
 5.1.4 Height Detection
 5.1.5 Metrological Characteristics
 5.1.5.1 Spot Size
 5.2 Instrumentation
 5.2.1 Lateral Scanning Configurations
 5.2.1.1 Profile Measurement
 5.2.1.2 Areal Measurement
 5.2.2 Optoelectronic Controller
 5.2.3 Optical Head
 5.2.4 Light Source
 5.2.5 Chromatic Objective
 5.2.6 Spectrometer
 5.2.7 Optical Fibre Cord
 5.3 Instrument Use and Good Practice
 5.3.1 Calibration
 5.3.1.1 Calibration of Dark Level
 5.3.1.2 Linearisation of the Response Curve
 5.3.1.3 Calibration of the Height Amplification Coefficient
 5.3.1.4 Calibration of the Lateral Amplification Coefficient
 5.3.1.5 Calibration of the Hysteresis in Bi-directional Measurement
 5.3.2 Preparation for Measurement
 5.3.3 Pre-processing
 5.4 Limitations of the Technique
 5.4.1 Local Slopes
 5.4.2 Scanning Speed
 5.4.3 Light Intensity
 5.4.4 Non-measured Points
 5.4.5 Outliers
 5.4.6 Interference
 5.4.7 Ghost Foci
 5.5 Extensions of the Basic Principles
 5.5.1 Thickness Measurement
 5.5.2 Line and Field Sensors
 5.5.3 Absolute Reference
 5.6 Case Studies
 Acknowledgements
 References
 6 Point Autofocus Instruments Katsuhiko Miura, Atsuko Nose
 6.1 Basic Theory
 6.2 Instrumentation
 6.3 Instrument Use and Good Practice
 6.3.1 Comparison with Roughness Material Measures
 6.3.2 Three-Dimensional Measurement of Grinding Wheel Surface Topography
 6.4 Limitations of PAI
 6.4.1 Lateral Resolution
 6.4.2 Vertical Resolution
 6.4.3 The Maximum Acceptable Local Surface Slope
 6.5 Extensions of the Basic Principles
 6.6 Case Studies
 6.7 Conclusion
 References
 7 Focus Variation Instruments Franz Helml
 7.1 Introduction
 7.2 Basic Theory
 7.2.1 How Does It Work?
 7.2.2 Acquisition of Image Data
 7.2.3 Measurement of 3D Information
 7.2.4 Post-processing
 7.2.5 Handling of Invalid Points
 7.3 Difference to Other Techniques
 7.3.1 Difference to Imaging Confocal Microscopy
 7.3.2 Difference to Point Auto Focusing Techniques
 7.4 Instrumentation
 7.4.1 Optical System
 7.4.2 CCD Sensor
 7.4.3 Light Source
 7.4.4 Microscope Objective
 7.4.5 Driving Unit
 7.4.6 Practical Instrument Realisation
 7.5 Instrument Use and Good Practice
 7.6 Limitations of the Technology
 7.6.1 Translucent Materials
 7.6.2 Measurable Surfaces
 7.7 Extensions of the Basic Principles
 7.7.1 Repeatability Information
 7.7.2 High Radiometric Data Acquisition
 7.7.3 2D Alignment
 7.7.4 3D Alignment
 7.8 Case Studies
 7.8.1 Surface Texture Measurement of Worn Metal Parts
 7.8.2 Form Measurement of Complex Tap Parameters
 7.9 Conclusion
 Acknowledgements
 References
 8 Phase Shifting Interferometry Peter de Groot
 8.1 Concept and Overview
 8.2 Principles of Surface Measurement Interferometry
 8.3 Phase Shifting Method
 8.4 Phase Unwrapping
 8.5 Phase Shifting Error Analysis
 8.6 Interferometer Design
 8.7 Lateral Resolution
 8.8 Focus
 8.9 Light Sources
 8.10 Calibration
 8.11 Examples of PSI Measurement
 References
 9 Coherence Scanning Interferometry Peter de Groot
 9.1 Concept and Overview
 9.2 Terminology
 9.3 Typical Configurations of CSI
 9.4 Signal Formation
 9.5 Signal Processing
 9.6 Foundation Metrics and Height Calibration for CSI
 9.7 Dissimilar

<<表面形貌的光学测量>>

Materials9.8 Vibrational Sensitivity9.9 Transparent Films9.10 Examples9.11 ConclusionReferences10 Digital Holographic Microscopy Tristan Coolmb,Jonas K ü hn10.1 Introduction10.2 Basic Theory10.2.1 Acquisition10.2.2 Reconstruction10.3 Instrumentation10.3.1 Light Source10.3.2 Digital Camera10.3.3 Microscope Objective10.3.4 Optical Path Retarder10.4 Instrument Use and Good Practice10.4.1 Digital Focusing10.4.2 DHM Parameters10.4.3 Automatic Working Distance in Reflection DHM10.4.4 Sample Preoaration and Immersion Liquids10.5 Limitations of DHM10.5.1 Parasitic Interferences and Statistical Noise10.5.2 Height Measurement Range10.5.3 Sample Limitation10.6 Extensions of the Basic DHM Principles10.6.1 Multi-wavelength DHM10.6.1.1 Extended Measurement Range10.6.1.2 Mapping10.6.2 Stroboscopic Measurement10.6.3 DHM Reflectometry10.6.4 Infinite Focus10.6.5 Applications of DHM10.6.5.1 Topography and Defect Detection10.6.5.2 Roughness10.6.5.3 Micro-optics Characterization10.6.5.4 MEMS and MOEMS10.6.5.5 Semi-transparent Micro-structures10.7 ConclusionsReferences11 Imaging Confocal Microscopy Roger Artigas11.1 Basic Theory11.1.1 Introduction to Imaging Confocal Microscopes11.1.2 Working Principle of an Imaging Confocal Microscope11.1.3 Metrological Algorithm11.1.4 Image Formation of a Confocal Microscope11.1.4.1 General Description of a Scanning Microscope11.1.4.2 Point Spread Function for the Limiting Case of an Infinitesimally Small Pinhole11.1.4.3 Pinhole Size Effect11.2 Instrumentation11.2.1 Types of Confocal Microscopes11.2.1.1 Laser Scanning Confocal Microscope Configuration11.2.1.2 Disc Scanning Confocal Microscope Configuration11.2.1.3 Programmable Array Scanning Confocal Microscope Configuration11.2.2 Objectives for Confocal Microscopy11.2.3 Vertical Scanning11.2.3.1 Motorised Stares with Optical Linear Encoders11.2.3.2 Piezoelectric Stages11.2.3.3 Comparison between Motorised and Piezoelectric Scanning Stages11.3 Instument Use and Good Practice11.3.1 LocatiOn of an Imaging Confocal Microscope11.3.2 Setting Up the Sample11.3.3 Setting the Right Scanning Parameters11.3.4 Simultaneous Detection of Confocal and Bright Field Images11.3.5 Sampling11.3.6 Low Magniflcation against Stitching11.4 Limitatioas of Imaging Confocal Microscopy11.4.1 Maximum Detectable Slope on Smooth Surfaces11.4.2 Noise and Resolution in Imaging Confocal Microscopes11.4.3 Errors in Imaring Confocal Microscopes11.4.3.1 Objective Flatness Error11.4.3.2 Calibration of the Flatness Error11.4.3.3 Measurements on Thin Transparent Materials11.4.4 Lateral Resolution11.5 Measurement of Thin and Thick Film with Imaging Confocal Microscopy11.5.1 Introduction11.5.2 Thick Films11.5.3 Thin Films11.6 Case Study:Roughness Prediction on Steel PlatesReferences12 Light Scattering Methods Theodore V.Vorburger,Richard Silver,Rainer Brodmann,Boris Brodmann,J?rg Seewig12.1 Introduction12.2 Basic Theory12.3 Instrumentation and Case Studies12.3.1 Early Developments12.3.2 Recent Developments in Instrumentation for Mechanical Engineering Manufacture12.3.3 Recent Developments in Instrumentation for Semiconductor Manufacture(Optical Critical Dimension)12.4 Instrument Use and Good Practice12.4.1 SEMI MF 1048-1109(2009)Test Method for Measuring the Effective Surface Roughness of Optical Components by Total Integrated Scattering12.4.2 SEMI ME 1392-1109(2009)Guide for Angle-Resolved Optical Scatter Measurements on Specular or Diffuse Surfaces12.4.3 ISO10110-8:2010 Optics and Photonics-Preparation of Drawings for Optical Elements and Systems-Part 8:Surface Texture12.4.4 Standards for Gloss Measurement12.4.5 VDA Guideline 2009,Geometrische Produktspezifikation Oberfl?chenbeschaffenheit Winkelaufgel?ste Streulichtmesstech-nik Definition,Kenngr? en und Anwendung(Light Scattering Measurement Technique)12.5 Limitations of the Technique12.6 Extensions of the Basic PrinciplesAcknowledgementsReferencesIndex

<<表面形貌的光学测量>>

版权说明

本站所提供下载的PDF图书仅提供预览和简介，请支持正版图书。

更多资源请访问:<http://www.tushu007.com>