

<<HSE警示录>>

图书基本信息

书名：<<HSE警示录>>

13位ISBN编号：9787502183486

10位ISBN编号：7502183485

出版时间：2011-3

出版时间：石油工业出版社

作者：中国石油海外勘探开发公司 编

页数：244

版权说明：本站所提供下载的PDF图书仅提供预览和简介，请支持正版图书。

更多资源请访问：<http://www.tushu007.com>

## <<HSE警示录>>

### 内容概要

继2010年7月印发《HSE警示录》之后，又推出了《HSE警示录(二)》。书中的47起事故事件就发生在近两年，发生在我们身边。事故的当事人、受害人有的是我们的同事、朋友，有的是为我们提供服务的承包商、分包商员工。一次小小的疏忽、一个简单的错误、一个不安全的行为，就可能酿成一起事故，造成无法挽回的人身伤亡或重大财产损失，毁掉个人的生命、家庭的幸福、企业的安定、社会的和谐。教训之深刻，后果之惨重，令我们痛心，更令我们反思。

## &lt;&lt;HSE警示录&gt;&gt;

## 书籍目录

Group 1 Caught In, Under or Between  
Worker Caught Between Truck and Skid Pump  
Foreman Pressed by Heavy Electrical Cabinet  
Pipe Yard Worker Suffered Thumb Injury  
Fingers Crushed by Roller  
Hand Pinched during Assembling Work  
Group 2 Cut, Puncture, Scrape  
Finger Joint Lost When Shutting off Wood Cutting  
Machine  
Group 3 Explosions or Burns  
Vacuum Truck Explosion  
Inflammation during Tanker Loading  
Refrigerator Truck Explosion  
Burn by Fire from Gas Leakage  
Automotive Technician Injured in Tire Explosion  
Driver Injured by Tyre Rupture  
Battery Explosion  
Operator Burnt by Steam  
Burn by Hot Formation Water  
Group 4 Exposure: Electrocutation  
Worker Killed by Overhead Power Line  
Group 5 Exposure: Noise, Pressure, Chemical,  
Biological, Vibration  
Bulldozer Operator Attacked by Wasps  
Escape from H<sub>2</sub>S Poisoning  
Bathroom Cleaner Suffered Eye Injury  
Group 6 Falls From Height  
Assistant Welder Fell From Height  
Security Guard Fell into a Cellar  
Group 7 Overexertion/Strain  
Back Injured When Lifting Boxes  
Group 8 Slips and Trips(at the same height)  
Burn after Slip in Kitchen  
Group 9 Struck By  
Driller Assistant Hit by Pipe Wrench  
Hand Injury during Casing Running  
Construction Worker Hit by Tent Frame  
Operator Struck by Broken Knuckle Joint  
Leg Injured by Swinging Pipe  
Welder Injured By Plate Falling from Drill Floor  
Group 10 Vehicle Crashes  
Fatal Traffic Accident at Field Bypass Road  
Collision Between a Dump Truck and a Fuel Tanker  
Fatal Traffic Accident Due to Overspeeding  
Worker Killed When Sheltering under Truck

<<HSE警示录>>

Security Patrolling Vehicle Accident  
Rollover Accident during Rig Move  
Group 11 Non-injurious Accident  
Exploratory Well Blowout during Production  
Testing  
Pipeline Leakage  
Oil Spilled from Vent Pond  
Pollution Resulted from Oil Well Blow-out  
Explosion of Buffer Tank in Metering Station  
Fire from Tanker Welding  
Fire Incident from Welding Operation  
Meeting Room Fire  
Scrap Yard Fire  
Bakery Container Fire  
Fiber Optical Cable Damaged by Excavator  
Group 12 Near Miss  
Excavation Near Miss Due to Non-compliance

<<HSE警示录>>

版权说明

本站所提供下载的PDF图书仅提供预览和简介，请支持正版图书。

更多资源请访问:<http://www.tushu007.com>